

APPENDIX D

SITE PHOTOGRAPHS



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:41 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking east/southeast toward General Chemical across the Facility. Topography is generally flat and consists of a rotomill and slag mix material.		



PHOTOGRAPH:		PHOTOGRAPHER:	
DATE/TIME:	8/24/2005	10:41 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking west across former slag stockpiled area located near the northwest portion of the Facility. Garcia's Trucking is in the background.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:27 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Fenced-in area located on eastern portion of the Facility across Kingshighway and the former Biggs Brothers Service Station		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:28 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking east towards the former Biggs Brothers Service Station and General Chemical Corporation		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:38 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Northwestern portion of the Facility looking at cross-section of access road consisting of mixture of roto-mill and slag.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:39 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking west-southwest from stockpiled slag area at access road elevation containing mixture of slag and roto-mill.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie L. Luna
DATE/TIME:	8/24/2005 0933		
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking at stained foundation wall associated with historic plant operations.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie L. Luna
DATE/TIME:	8/24/2005 0934		
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Rubble associated with historic plant operations located in the center of the Facility, west of the historic rail line.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:35 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Rubble associated with historic plant operations located in the center of the Facility, west of the historic rail line.		

PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	0936		
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:			




PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:43 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking north toward former building footprint and slag pile in background.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:44 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking toward low-lying, unvegetated area located north of stockpiled slag area adjacent to Maryland Parkway in Grids 39 and 40.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:15 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Slag pile located on northern portion of the Facility in relation to a six-foot person.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:15 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Close up cross section of slag pile located on northern portion of Facility.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/8/2006	11:18 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Interstate Tire Retread, Inc. building located near the southeastern portion of the Facility in Grids 70 and 71.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:29 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking south toward Interstate Tire Retread, Inc. across East Ditch 1. Rubble from historic ore and maintenance buildings in foreground.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/8/2006	10:12 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Surface sampling collection activities and sampling locate using GPS.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/8/2006	10:14 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Surface sample collection from upper one inch of material over one-foot square area using stainless-steel trowel		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/5/2006	9:59 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Subsurface sampling activities using a Geoprobe.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/14/2006	10:47 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Geologic logging of borehole and PID analysis of Macro-Core sampler from Geoprobe activities.		



PHOTOGRAPH:		PHOTOGRAPHER:	Mike Carlson
DATE/TIME:	6/19/2006	9:42 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Hand auger sampling conducted in the low-lying unvegetated area located at the northern boundary of the Facility.		



PHOTOGRAPH:		PHOTOGRAPHER:	Mike Carlson
DATE/TIME:	6/14/2006	4:34 PM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Materials retrieved via hand augering activities were placed on plastic in sequence for identification and sampling.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/19/2006	2:03 PM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Installation of monitoring well MW-02 using 4.25-inch inner diameter, hollow-stemmed auger.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/19/2006	2:54 PM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Decontamination of augers and the near completion of installing MW-02.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	7/7/2006	2:02 PM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Slug test setup at P-03 utilizing a 36-inch, sand-filled PVC slug		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	7/7/2006	11:30 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Slug testing activities utilizing the Hermit 3000 datalogger and transducer.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	7/7/2006	8:19 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Groundwater sampling activities using the YSI, flow-through cell, and peristaltic pump conducted at MW-01.		



PHOTOGRAPH:	18	PHOTOGRAPHER:	Jeff Stofferahn
DATE/TIME:	7/7/2006	8:18 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Groundwater samples were collected via low-flow peristaltic pump.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/22/2006	8:57 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Collection of five-point composite sample at residential property.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/22/2006	9:31 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Homogenizing composite sample from residential property in stainless-steel bowl.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	6/8/2006	11:07 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Three concrete vaults located adjacent to XTRA's former machine shop in Grid 67.		



PHOTOGRAPH:		PHOTOGRAPHER:	Jeff Stofferahn
DATE/TIME:	6/8/2006	11:07 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Vent pipes attached to XTRA's former shop building, adjacent to the concrete vault area in Grid 67.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	3/27/2007	7:10 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Alleyway sampling in Alleyway Transect (AT)-8 using a Geoprobe.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	3/28/2007	8:11 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking east down AT-5 showing typical alleyway in Fairmont City, IL.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	1:00 PM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking northwest towards CSX Intermodal operations located adjacent to and south of the Facility.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	8/24/2005	9:30 AM	
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Looking south across East Ditch 1. Cargill Company (formerly Swift Agricultural Chemical Corp.) is visible in background.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	5/31/2006 2:39 PM		
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	Sample custodian activities conducted in sample trailer located on the Facility.		



PHOTOGRAPH:		PHOTOGRAPHER:	Melanie Gotto
DATE/TIME:	5/31/2006 2:39 PM		
PROJECT:	Remedial Investigation Report for the Old American Zinc Plant Site, Fairmont City, Illinois		
SUBJECT:	XRF screening in the sample trailer located on the Facility.		